

DIGITAL WEIGHT INDICATOR (NEMA 4)

ORDERING INFORMATION

Model No.	Description
3550-1	Digital Strain Meter with 85-265 Vac power input, two 10 Amp relays, peak hold, RS-232 Input/Output (Standard Unit)
3550-2	Digital Strain Meter with rechargeable battery power, two 10 Amp relays, peak hold, RS-232 Input/Output
3550-3	Digital Strain Meter with 12-48 Vdc power input, two 10 Amp relays, peak hold, RS-232 Input/Output

Note: When ordering specify full scale load capacity, units of measure, input sensitivity, and bridge resistance.

Example: 3550-1 digital meter with 85-265 Vac power input, two 10 Amp relays, peak hold, RS-232 Input/Output configures for 25,000 pound, 2-mv/V, 350 Ohm load cell bridge.

3550 - 1 (25,000 POUNDS, 2-mv/V, 350 Ohms)

